

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

Name of the School

St. Joseph International
School

1. Name of the Officer

Swathy Singh

2. Location

Kollam, Kandalas, Chittumala

3. Period for which the certificate is issued

2023-24

4. Types of building

Permanent RCC bldg.

5. Nature of defect if any

a) Foundation and basement

1. (a) G.F. 35.3X16.15m

(b) F.F 35.3X16.15m

b) Superstructure

2. (a) G.F 47.85X16.15

(b) F.F 47.85X16.15

c) Doors and windows

d) Wood work wrought and put up

e) Roof

f) Flooring

g) Miscellaneous (Cracks if any)

Nil as of now (at the time of inspection)

6. Any Major defects notices which will render the building unsafe in any manner

Nil

7. Whether maintenance works have been done properly

Yes, satisfactory

8. Whether the structure is sound or not for conducting classes

Sound under normal cond
& weather conditions.

- Note:-
1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc.
 2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

Entry of students to back side of the building is blocked (as per latest site visit). Based on that fitness certificate is CERTIFICATE issued.

Certified that the School was inspected by me on 05/05/23.

and found to be fit / unfit to conduct classes for the period 2023-24

for the reason stated above.

Place: East Kallada.

(Seal)

Date: 05/05/2023.

OFFICE OF THE ASSISTANT ENGINEER
L.I.D & E.W SECTION
EAST KALLADA GRAMA PANCHAYATH
PIN: 691502

Swathy Singh

Ass. **SWATHY SINGH**
ASSISTANT ENGINEER
L.I.D & E.W SECTION
EAST KALLADA GRAMA PANCHAYATH
PIN: 691502