

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

SRUTHY SINGH  
S.T. Joseph International School,  
chittumala, Kallam, Kundara

Permanent RCC bldg

1. a) G.F. 35.30 X 16.15

b) 35.30 X 16.15 F.F.

2. a) G.F. 47.85 X 16.15

b) F.F. 47.85 X 16.15

5. Period for which the certificate is issued

2024-25

6. Nature of defects, if any

a) Foundation and basement

b) Superstructure

c) Doors and Windows

d) Wood work wrought and put up

e) Roof

f) Flooring

g) Miscellaneous (Cracks, etc.)

Nil

7. Any major defects noticed which will render the building unsafe in any manner

Nil

8. Whether maintenance works have been done properly

Yes

9. Whether the structure is sound or not for conducting classes

Sound under normal wind & weather conditions

**Note :** 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

Entry of students to the backside is found locked at the time of inspection. Based on that following fitness certificate is issued.

## CERTIFICATE

certified that the school building was inspected by me on 23/05/2024 and

found to be fit / unfit to conduct classes, for the period 2024-25 for the reasons stated above.

Place : East kallada

Date : 24/05/2024

(Seal)

OFFICE OF THE ASSISTANT ENGINEER  
L.I.D & E.W. SECTION  
EAST KALLADA GRAMA PANCHAYATH  
PIN: 691502

SRUTHY SINGH

Assistant Engineer  
L.I.D & E.W. SECTION  
EAST KALLADA GRAMA PANCHAYATH  
PIN: 691502